




No.


The Spare Parts Database is maintained with great care. Nonetheless, errors cannot be completely ruled out. If you notice an error, please let us know. We reserve the right to make technical changes.

Mitsubishi Electric Spare Parts



	Part No.	RoHS	SAP	Part Name	Specifications	Qty	Remarks	Wiring diagram symbol
1	R01E46221	G	209170	FAN MOTOR <316188> <325089>		2		MF1,2
2	R01E06115	G	209155	PROPELLER FAN PUHZ-P-YHA <		2		
3	R01E09097	G	191536	NUT<G>PUHZ-RP14<226021><322818		2		
4	T7WE45408	G	209191	HEAT EXCHANGER PUHZ-P-YHA		1		
5	T97415756	G	209193	COMPRESSOR ANB52FFJMT <220NB52FFJMT		1	with RUBBER MOUNTS	MCS
6	R01E13410	G	191488	STOP VALVE <G> PUHZ-RP140Y 3/8 (LIQUID)		1		
7	R01E13411	G	209166	BALL VALVE 3/4 PUHZ-P-YHA <G>		1		
8	R01E14201	G	207561	THERM PUHZ-RPYHA2-1<G><40		1		TH4
9	R0145L450	G	206063	STRAINER PUMP P <G>		1		
10	R01E59440	G	238221	ACCUMULATOR <G>		1		
11	R01E10467	G	194119	MUFFLER PUHZ <G>		1		
12	R01E24413	G	215950	CHARGE PLUG <H>		2		
13	R01H19401	G	209171	LEV PUHZ-P-YHA<G>		1		
14	R01E50242	G	191506	LEVCOIL <G> PUHZ-RP140YHA2		1		LEV-A
15	R01H01202	G	191509	THERMISTOR <G> PUHZ-RP140YHA2		1		TH6,7
16	R01E15403	G	222135	4 WAY VALVE <244829>		1		
17	T7WE39242	G	209720	SOLENOID COIL PUHZ <G><414720>		1		21S4
18	R01E06208	G	191533	HIGH PRESSURE <G> <409263>	OFF 4.14MPa	1		63H
19	T7WE30716	G	214453	TERMINAL BLOCK <H>	5P (L1,L2,L3,N,PE)	1		TB1
20	R01E19246	G	194111	TERMINAL BED PUHZ <G>	3P(S1,S2,S3)	1		TB2
21	T7WE16259	G	213733	REACTOR <H>		1		ACL4
22	T7WE24346	G	209189	NOISE FILTER PUHZ-P-YHA <G>		1		N.F.
23	T7WE55315	G	209192	CONTROL BOARD PUHZ <225046>		1		C.B.
24	R01 30L 241	G	194097	FUSE HOLDER <H>		2		
25	R01E07239	G	194103	FUSE PUHZ <G>	250V 15A	2		FUSE1,2
26	R01E10233	G	191538	RESISTOR <H>		1		RS
27	T7WE21255	G	209184	CAPACITOR PUHZ-P-YHA<G>		2		CB1,2
28	ZD#BK00B702	G		ELECTRICAL PARTS BOX		1		
29	T7WE44313	G	209190	POWER BOARD PUHZ <225034>		1		P.B.
30	T7WE13259	G	194027	REACTOR <H>		1		DCL
31	R01E96202	G	194706	THERMISTOR PUHZ-RP-VHA2 <G>		1		TH3
32	R01E14239	G	225798	FUSE <H>	6.3A 250V	2		F3,4

The Spare Parts Database is maintained with great care. Nonetheless, errors cannot be completely ruled out. If you notice an error, please let us know. We reserve the right to make technical changes.



No.	Part No.	RoHS	SAP	Part Name	Specifications	Qty	Remarks	Wiring diagram symbol
1	ZD#DG12F536H12			F.ST SCREW	(5x12)	1		
2	R01E20662	G	209167	SI PAN(L)PUHZ-P-YHA<G><2523>		1		
3	T7WE03691	G	191512	INTAKE GRILL <G> PUHZ-RP140YHA		2		
4	T7WE06667	G	191513	FRONT PANEL <G> PUHZ-RP140		1		
5	T7W E11 130	G	209173	MOTOR SUPPORT PUHZ-P-YHA <G>		1		
6	R01 E31 686	G	194035	BASE PUHZ-RP140YHA2<G><219>		1		
7	ZD#BK00C374GM3			SEPARATOR		1		
8	ZD#BK00C375	G		VALVE BED ASSY		1		
8	R01E01655	G	191529	HANDLE <G> PUHZ-RP140YHA2		2		
10	R01E13658	G	191492	COVER PANEL <G> PUHZ-RP140		1		
11	R01E11658	G	194077	COVER PANEL (REAR) <219251>		1		
12	R01E29661	G	209168	SIDE PANEL(R) PUHZ-P-YHA<G>		1		
13	T7WE07667	G	209172	SERVICE PANEL PUHZ-P-YHA <G>		1		
14	ZD#BK79G177	G		LABEL		1		
15	R01E07698	G	191534	REAR GUARD <G> PUHZ-RP140YHA2		1		

The Spare Parts Database is maintained with great care. Nonetheless, errors cannot be completely ruled out. If you notice an error, please let us know. We reserve the right to make technical changes.

16	R01E28641	G	219400	TOP PANEL PUMY <275515>		1		
17	R01E02655	G	191531	HANDLE <G> PUHZ-RP140YHA2		1		